

In the parish of Ansty:

- There are nearly 6 miles of public 'Rights of Way'
- 81% of our Rights of Way are currently satisfactory
- There are 36 stiles to climb and 4 gates to open!

Our footpaths, bridleways and byways are set in beautiful and vastly varying landscapes from high chalk downs, greensand ridges, steep sided coombes, sunken lanes and woodlands. Some are relaxing walks; others quite challenging and they are there for your use! Large areas of the slopes of the chalk downs are classed as 'access land'.

So far in the last year or so:

- √ 4 sections of our parish footpaths have been cleared
- √ 8 new stiles have been installed, replacing old rotten ones
- √ 2 new kissing gates have been installed.

These upgrades are part of Wiltshire Council's initiative to improve accessibility along all of our 'rights of way' as well as encouraging all of us to become healthier and fitter by using them! To this end volunteers work with Wiltshire Council to help supply labour (and even expertise) whilst the Council supplies tools, equipment and guidance as to what needs doing.

In Ansty a small group of volunteers have got together to do additional work on our local ROWs as well as further afield. Regular clearance and maintenance has to be done year on year to keep our 6 miles of footpaths a pleasure to use.

Projects in the pipeline for 2016:

- Replacing two missing FP post and finger signs. (FP1 High St to Yule Lane; FP6 off A30 to Shave Lane)
- Installing fence and steps on upper section of FP2
- Clearing fallen trees and debris blocking FP 11 in 12 Acre Copse
- New signs and access to FP3 bridleway
- Improving access via FP 8 from Kings Lane to Ansty Coombe Lane
- General maintenance and footpath clearance throughout the growing season

Long term project:

. Upgrading FP5 from Shave Lane to Whitesheet Hill. This is a lovely but quite challenging walk.

Look out for the publication of our circular walks around the parish!

If you would like to become involved in helping us look after our 'rights of way' in Ansty contact:

rgwilk@hotmail.co.uk (parish footpath subcommittee) or anneandtimmartin@gmail.com

Other useful links:

Ansty Parish Wiltshire.

FOOTPATH SURVEY OCTOBER 2015

By Rob Wilkinson and Tim Martin

Parish Footpath	Accessibilty Sign Posts			Sig	nage Provisi	ion	Stiles	& Gates		Achieved in 2014/15	Observations	
		%				Acc Signs	W Markers		Stiles	Gates	Action needed. A new signpost is needed	In October 2015 contractors ploughed
ED4	Satisfactory	100	Ideal No	2	Ideal No	0	0	Total No	1	0	and at least a wooden safety rail to stop	through the stile and a signpost has
FP1	Difficult	0	In place	1	In place	0	0	Need repair	0	0	walkers stepping straight on to the road. It	gone missing (lifted out of its hole.
	Impassable	0	Needed	1	Needed	0	0	Need renewal*	1	0	is possible that a stile may be needed - but	*Stile might not be needed.
FP1 Ansty High St to	o Yule Hill. 0.3k	m OS F	Ref: ST 95527	71 to 95	7273						not currently.	
FP1 crosses single												
Parish Footpath	Accessib	ilty	Sign P	osts	Sig	nage Provisi	ion	Stiles	& Gates		Achieved in 2014/15	Observations
		%				Acc Signs	W Markers		Stiles	Gates	Footpath lower sections have been cleared	Dangerous access to (and from road)
EDO	Satisfactory	80	Ideal No	1	Ideal No	0	2	Total No	1	0	by Avs. Action needed: Still some more	requires at least a wooden rail for
FP2	Difficult	20	In place	1	In place	0	0	Need repair	1	0	clearance possibly.	safety reasons.
	Impassable	0	N eeded	0	N eeded	0	2	Need renewal	0	0		
FP2 Ansty High St to	o Swallowcliffe	bounda	ary. 0.5 km. (OS Ref:	ST 957265 to	963268						
FP2 traverses very							d junction v	vith road				
Parish Footpath	Accessib	ilty	Sign P	osts	Sig	nage Provisi	ion	Stiles	& Gates		Achieved in 2014/15	Observations
Parish Footpath	Accessib	ilty %	Sign P	osts	Sig	nage Provisi Acc Signs		Stiles	& Gates Stiles	Gates	Achieved in 2014/15 Action needed. This bridleway is not fit for	Observations * Old Way mark signs need replacing;
	Accessib Satisfactory	•	Sign P	osts 2	Sig	•		Stiles Total No		Gates 0		* Old Way mark signs need replacing; Access signs need to be installed. A
FP3		%				Acc Signs	W Markers		Stiles		Action needed. This bridleway is not fit for	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to
	Satisfactory	% 0	Ideal No	2	Ideal No	Acc Signs	W Markers 8	Total No	Stiles 0	0	Action needed. This bridleway is not fit for purpose as things stand at the moment.	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a
FP3	Satisfactory Difficult Impassable	% 0 0 100	Ideal No In place Needed	2 0 2	Ideal No In place* Needed	Acc Signs 2 0 2	W Markers 8 0	Total No Need repair	Stiles 0 0	0	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a good bet. Currently no apparent
	Satisfactory Difficult Impassable - Swallowcliffe	% 0 0 100	Ideal No In place Needed	2 0 2	Ideal No In place* Needed	Acc Signs 2 0 2	W Markers 8 0	Total No Need repair	Stiles 0 0	0	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a
FP3 (Bridleway) A30	Satisfactory Difficult Impassable - Swallowcliffe	% 0 0 100 Bound ss on to	Ideal No In place Needed	2 0 2 OS Ref :	Ideal No In place* Needed ST 960261 to	Acc Signs 2 0 2	W Markers 8 0 8	Total No Need repair Need renewal	Stiles 0 0	0	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a good bet. Currently no apparent access: no sign/opening gate/or stile
FP3 (Bridleway) A30	Satisfactory Difficult Impassable - Swallowcliffe Dangerous acces	% 0 0 100 Bound ss on to	Ideal No In place Needed lary. 0.5 km.	2 0 2 OS Ref :	Ideal No In place* Needed ST 960261 to	Acc Signs 2 0 2 ST 964256	W Markers 8 0 8	Total No Need repair Need renewal	Stiles 0 0 0	0 0 0	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will be resolved.	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a good bet. Currently no apparent access: no sign/opening gate/or stile off A30
FP3 (Bridleway) A30 Poor visibility and E Parish Footpath	Satisfactory Difficult Impassable - Swallowcliffe Dangerous acces	% 0 0 100 Bound ss on to	Ideal No In place Needed lary. 0.5 km.	2 0 2 OS Ref :	Ideal No In place* Needed ST 960261 to	Acc Signs 2 0 2 0 ST 964256	W Markers 8 0 8	Total No Need repair Need renewal	Stiles	0 0 0	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will be resolved. Achieved in 2014/15	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a good bet. Currently no apparent access: no sign/opening gate/or stile off A30 Observations
FP3 (Bridleway) A30	Satisfactory Difficult Impassable - Swallowcliffe Dangerous access	% 0 100 Bound ss on to	Ideal No In place Needed lary. 0.5 km. A 30 Sign P	2 0 2 OS Ref:	Ideal No In place* Needed ST 960261 to Sig	Acc Signs 2 0 2 0 ST 964256 mage Provisi Acc Signs	W Markers 8 0 8 ion W Markers	Total No Need repair Need renewal Stiles Total No	Stiles 0 0 0 8 Gates Stiles	0 0 0	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will be resolved. Achieved in 2014/15 Action needed; Considerable clearance of a	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a good bet. Currently no apparent access: no sign/opening gate/or stile off A30 Observations Difficult access from Alvediston road. V steep needs a wooden rail or even steps; walkers haul on the sign post:
FP3 (Bridleway) A30 Poor visibility and E Parish Footpath	Satisfactory Difficult Impassable - Swallowcliffe Dangerous acces Accessib Satisfactory Difficult	% 0 0 100 Bound ss on to iilty % 80 5	Ideal No In place Needed lary. 0.5 km. O A 30 Sign P Ideal No In place	2 0 2 OS Ref:	Ideal No In place* Needed ST 960261 to Sig	Acc Signs 2 0 2 0 ST 964256 mage Provisi Acc Signs 2 0	W Markers 8 0 8 ion W Markers 0	Total No Need repair Need renewal Stiles Total No Need repair	Stiles 0 0 0 8 Gates Stiles 2	0 0 0 Gates	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will be resolved. Achieved in 2014/15 Action needed; Considerable clearance of a short section off the Alvediston Rd needs to be cleared to allow access to the Scarp slope; Some remedial work needs to be	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a good bet. Currently no apparent access: no sign/opening gate/or stile off A30 Observations Difficult access from Alvediston road. V steep needs a wooden rail or even steps; walkers haul on the sign post: loose post. Virtually impassable for
FP3 (Bridleway) A30 Poor visibility and E Parish Footpath FP4	Satisfactory Difficult Impassable - Swallowcliffe Dangerous acces Accessib Satisfactory Difficult Impassable	% 0 0 100 Bound ss on to iilty % 80 5 15	Ideal No In place Needed lary. 0.5 km. A 30 Sign P Ideal No In place Needed	2 0 2 OS Ref:	Ideal No In place* Needed ST 960261 to Sig Ideal No In place Needed	Acc Signs 2 0 2 ST 964256 nage Provisi Acc Signs 2 0 2	W Markers 8 0 8 ion W Markers 0 0 0	Total No Need repair Need renewal Stiles Total No Need repair Need repair	\$tiles 0 0 0 & Gates \$tiles 2 0	0 0 0 Gates 0	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will be resolved. Achieved in 2014/15 Action needed; Considerable clearance of a short section off the Alvediston Rd needs to be cleared to allow access to the Scarp slope; Some remedial work needs to be done with the stile and signpost at the	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a good bet. Currently no apparent access: no sign/opening gate/or stile off A30 Observations Difficult access from Alvediston road. V steep needs a wooden rail or even steps; walkers haul on the sign post: loose post. Virtually impassable for about 30m due to scrub. Some attempt
FP3 (Bridleway) A30 Poor visibility and E Parish Footpath	Satisfactory Difficult Impassable - Swallowcliffe Dangerous acces Accessib Satisfactory Difficult Impassable ton road hill to	% 0 0 100 Bound is on to silty % 80 5 15 top just	Ideal No In place Needed lary. 0.5 km. A 30 Sign P Ideal No In place Needed t before by-w	2 0 2 OS Ref: osts 2 2 0	Ideal No In place* Needed ST 960261 to Sig Ideal No In place Needed sing road. 0.2	Acc Signs 2 0 2 0 ST 964256 nage Provisi Acc Signs 2 0 2 28km ST 9633	W Markers 8 0 8 ion W Markers 0 0 0	Total No Need repair Need renewal Stiles Total No Need repair Need repair	\$tiles 0 0 0 & Gates \$tiles 2 0	0 0 0 Gates 0	Action needed. This bridleway is not fit for purpose as things stand at the moment. However, we are optomistic that things will be resolved. Achieved in 2014/15 Action needed; Considerable clearance of a short section off the Alvediston Rd needs to be cleared to allow access to the Scarp slope; Some remedial work needs to be	* Old Way mark signs need replacing; Access signs need to be installed. A small section of permissive path to enable access to bridleway looks a good bet. Currently no apparent access: no sign/opening gate/or stile off A30 Observations Difficult access from Alvediston road. V steep needs a wooden rail or even steps; walkers haul on the sign post

Parish Footpath	Accessibilty		Sign P	Sign Posts		nage Provisi	ion	Stiles & Gates			Achieved in 2014/15 Action underway. Extensive Survey 2015 to	Observations Alternative footpath suggested; current
			Acc Signs W Markers			Stiles	Gates					
FP5	Satisfactory	75	Ideal No	4	Ideal No	3	14	Total No	6	1	try and breathe life into this RoW. There are	path: poorly defined at beginning; stiles
ГРЭ	Difficult	25	In place	0	In place	0	0	Need repair	3	0	several suggestions in the pipeline re how	in poor state; access up scarp slope
	Impassable	0	Needed	4	Needed	3	14	Need renewal	3	0	to tackle this FP. Productive meeting in October 2015 with LandOwner Peter Dalton.	difficult initially - footpath clearance needed; difficult to see 'way'.
FP5 (Bridleway) Sha	ave Lane off A30	to foot	of Ansty Do	wn.1.02	km. ST 9532	51 to ST 949	245				Frankly all current stiles need renewing or	Alternative FP along NE edge of
Currently difficult a			•					Much needs to	be done		substantial repair. Footpath clearance and a	Windbreak. Original byway not viable.
Parish Footpath	Accessib		Sign P			nage Provisi			& Gates		Achieved in 2014/15	Observations
•		%				Acc Signs			Stiles	Gates	Footpath was totally impassable	Ansty signpost went missing around
EDC	Satisfactory	95	Ideal No	2	Ideal No	0	4	Total No	4	0	(brambles/vegetation) almost throughout its	October 14th 2015; Other signpost off
FP6	Difficult	5	In place	0	In place	0	0	Need repair	0	0	length in September 2015; Cleared by Avs	Shave Lane pointing the way to FP 6
	Impassable	0	Needed	2	Needed	0	4	Need renewal	3	0	in October 2015. Action needed:Signposts	disappeared several years ago. New
FP6 Just south of A	•			have La		Copse), 0, 7	0-km. OS R		ST 9532		needs replacing and 3 stiles need	Landowner in October.
Care needed crossir	•	-			(= 0	. Сросу.		··· · · · · · · · · · · · · · · · · ·			repair/renewing	
Parish Footpath	Accessib	ilty	Sign P	osts	Sigr	nage Provisi	ion	Stiles	& Gates		Achieved in 2014/15	Observations
		%				Acc Signs	W Markers		Stiles	Gates	Footpath from Ansty Coombe Lane to old	A pleasant walk on a summer's
FP7	Satisfactory	100	Ideal No	2	Ideal No	0	12	Total No	4	0	Polo practice fields cleared in September	evening. Forms a short circular route
	•			•	In place	0	0	Nand namein		0	2015 by Avs. No urgent action needed	with Ansty Coombe Lane. OS map
	Difficult	0	In place	2	III blace	U	U	iveed repair	1	U	3	
	Difficult Impassable	0	In place Needed	0	In place Needed	0	12	Need repair Need renewal	1 1	0	currently.	representation incorrect. (For all the
FP7 Ansty Coombe	Impassable	0	N eeded	0	Needed	0	12	Need renewal	1 1 951258 t d	0	•	·
	Impassable Lane close to A	0 30 junct	N eeded	0	Needed	0	12	Need renewal	1 1 951258 t c	0	•	representation incorrect. (For all the
FP7 Ansty Coombe	Impassable Lane close to A	0 30 junct iews	N eeded	0 Coomb	Needed be Lane-Blind	0	12 oads. 0.96 k	Need renewal	1 1 951258 to & Gates	0	•	representation incorrect. (For all the
FP7 Ansty Coombe A delightful walk wi	Impassable Lane close to A th spectacular v	0 30 junct iews	Needed tion to Ansty	0 Coomb	Needed be Lane-Blind	0 Lane crossro	12 oads. 0.96 k	Need renewal		0 ST 954	currently.	representation incorrect. (For all the right reasons).
FP7 Ansty Coombe A delightful walk wi Parish Footpath	Impassable Lane close to A th spectacular v	0 30 junct iews iity	Needed tion to Ansty	0 Coomb	Needed be Lane-Blind	0 Lane crossro	12 oads. 0.96 k	Need renewal	& Gates	0 ST 954	Achieved in 2014/15 Stile off Kings Lane towards Ansty Coombe Lane installed in 2014 (WC). The FP section	representation incorrect. (For all the right reasons). Observations
FP7 Ansty Coombe A delightful walk wi	Impassable Lane close to A: th spectacular v Accessib	0 30 junct iews iilty %	Needed tion to Ansty Sign P	0 Coomb	Needed De Lane-Blind Sign	0 Lane crossro nage Provisi Acc Signs	oads. 0.96 k ion W Markers	Need renewal m. OS Ref: ST Stiles	& Gates Stiles	0 ST 954 Gates	Achieved in 2014/15 Stile off Kings Lane towards Ansty Coombe Lane installed in 2014 (WC). The FP section from Kings Lane to Squalls restricted	representation incorrect. (For all the right reasons). Observations Predominantly a locals walk; also used by some runners. Limited access though due to deep bog in
FP7 Ansty Coombe A delightful walk wi Parish Footpath	Impassable Lane close to A: th spectacular v Accessib Satisfactory Difficult	0 30 junct iews vilty % 25	Needed tion to Ansty Sign P	0 Coomb	Needed De Lane-Blind Sign Ideal No	0 Lane crossro nage Provisi Acc Signs 0	12 oads. 0.96 k ion W Markers	Need renewal tm. OS Ref: ST Stiles Total No	& Gates Stiles	0 ST 954 Gates	Achieved in 2014/15 Stile off Kings Lane towards Ansty Coombe Lane installed in 2014 (WC). The FP section from Kings Lane to Squalls restricted byway cleared September 2015 by Avs.	Observations Predominantly a locals walk; also used by some runners. Limited access though due to deep bog in middlesection. See separate notes
FP7 Ansty Coombe A delightful walk wi Parish Footpath FP8	Impassable Lane close to A: th spectacular v Accessib Satisfactory Difficult Impassable	0 30 junct iews iilty % 25 75 0	Needed tion to Ansty Sign P Ideal No In place Needed	O Coomb	Needed Sign Ideal No In place Needed	Dane crossro	12 oads. 0.96 k ion W Markers 15 9 6	Need renewal tm. OS Ref: ST Stiles Total No Need repair Need renewal	& Gates Stiles 6 1	0 ST 954 Gates 1 0	Achieved in 2014/15 Stile off Kings Lane towards Ansty Coombe Lane installed in 2014 (WC). The FP section from Kings Lane to Squalls restricted byway cleared September 2015 by Avs. Action needed:A Causeway/Bridge is	representation incorrect. (For all the right reasons). Observations Predominantly a locals walk; also used by some runners. Limited access though due to deep bog in
P7 Ansty Coombe A delightful walk wi Parish Footpath	Impassable Lane close to A: th spectacular v Accessib Satisfactory Difficult Impassable Lane-Blind Lane	0 30 junct iews iilty % 25 75 0	Sign P Ideal No In place Needed	Coomb	Needed De Lane-Blind Sign Ideal No In place Needed The to Squalls Later	Danage Provision Acc Signs 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	12 oads. 0.96 k ion W Markers 15 9 6	Need renewal Total No Need repair Need renewal T 954266 to ST	& Gates Stiles 6 1	0 ST 954 Gates 1 0	Achieved in 2014/15 Stile off Kings Lane towards Ansty Coombe Lane installed in 2014 (WC). The FP section from Kings Lane to Squalls restricted byway cleared September 2015 by Avs.	Observations Predominantly a locals walk; also used by some runners. Limited access though due to deep bog in middlesection. See separate notes

Parish Footpath	Accessib	ilty	Sign P	osts	Sig	nage Provisi	ion	Stiles	& Gates		Achieved in 2014/15	Observations
		%				Acc Signs	W Markers		Stiles	Gates	Stile joining FP 15 from FP 9 renewed	Stile off Kings Lane needs some repai
FP9	Satisfactory	100	Ideal No	1	Ideal No	0	0	Total No	2	0	Summer 2015. Avs + WC	or even renewal. Exposed barbed
FP3	Difficult	0	In place	1	In place	0	0	Need repair	1	0		wire on and near Stile dangerously
	Impassable	0	Needed	0	Needed	0	0	Need renewal	0	0		exposed. Quite well used; stile rarely
FP9 Kings Lane to j		15 (Th	atchers Cotta	age). 0.(08 km. ST 9512	265 to 951266	6					used because makeshift gate usually open.
	_											орон.
Parish Footpath	Accessib	ilty	Sign P	osts	Sig	nage Provisi	ion	Stiles	& Gates		Achieved in 2014/15	Observations
		%				Acc Signs	W Markers		Stiles	Gates	No urgent action needed. Stile at entrance	The causeway could do with a couple
FP10	Satisfactory	95	Ideal No	2	Ideal No	0	2	Total No	1	0	to 12 Acre Copse renewed in summer 2015	of extra sleepers. A Signpost is
FFIU	Difficult	5	In place	0	In place	0	2	Need repair	0	0	Avs = WC; other stile off Ansty Coombe	needed to link Tisb64 restricted by way
	Impassable	0	Needed	2	Needed	0	0	Need renewal	0	0	Lane replaced by gate in late summer 2014	dogleg with Ansty FP 10. Quite well
					0.57.1	OC D-6-054	265 to 0/926	7			plus a sleeper causeway to help walkers	used.
FP10 Ansty Coombe	e Lane (Frogpon	d) to S	qualls Lane ı	restr by	way. 0.57 km.	05 Ket: 9512	200 10 34020	"			avoid had conditions	
FP10 Ansty Coombe	e Lane (Frogpon	d) to S	qualls Lane ı	estr by	way. 0.57 km.	US Ref: 9512	200 10 94020	,,			avoid bog conditions	
FP10 Ansty Coombe	e Lane (Frogpon Accessib		qualls Lane i			nage Provisi			& Gates		avoid bog conditions Achieved in 2014/15	Observations
							ion		& Gates Stiles	Gates	Achieved in 2014/15 Stile at entrance to 12 Acre Copse	Observations FP 11 has been blocked by fallen
Parish Footpath		ilty				nage Provisi	ion			Gates 1	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013.
	Accessib	ilty %	Sign P	osts	Sig	nage Provisi Acc Signs	ion W Markers	Stiles	Stiles		Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC.	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the
Parish Footpath	Accessib Satisfactory	ilty % 0	Sign P	osts	Sign Ideal No	nage Provisi Acc Signs 0	ion W Markers 7	Stiles Total No	Stiles 1	1	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs,WC	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting.
Parish Footpath	Accessib Satisfactory Difficult Impassable	ilty % 0 100 0	Sign P Ideal No In place Needed	osts 2 1 1 1	Sign Ideal No In place Needed	nage Provisi Acc Signs 0 0	ion W Markers 7 3 4	Stiles Total No Need repair Need renewal	Stiles 1 0	1 0	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs, WC and HG; Action Needed: Sleeper causeway needs to be longer; A post	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting. Either a New Post from Tis77 or at
Parish Footpath FP11	Accessib Satisfactory Difficult Impassable e Lane (Frogpon	ilty % 0 100 0	Sign P Ideal No In place Needed nct with FP	osts 2 1 1 Tis77 (1	Signal Ideal No In place Needed	nage Provisi Acc Signs 0 0 0 0 0	ion W Markers 7 3 4	Stiles Total No Need repair Need renewal	Stiles 1 0	1 0	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs,WC and HG; Action Needed: Sleeper	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting.
Parish Footpath FP11 Ansty Coombe	Accessib Satisfactory Difficult Impassable e Lane (Frogpon	ilty % 100 0 d) to jurees an	Sign P Ideal No In place Needed nct with FP	2 1 1 Tis77 (1	Sign Ideal No In place Needed I2 Acre Copse	nage Provisi Acc Signs 0 0 0 0 0	ion W Markers 7 3 4 DS Ref: 951	Stiles Total No Need repair Need renewal 265 to 948265	Stiles 1 0	1 0	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs,WC and HG; Action Needed: Sleeper causeway needs to be longer; A post waymarker is needed to indicate	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting. Either a New Post from Tis77 or at
Parish Footpath FP1 1 FP11 Ansty Coombe	Accessib Satisfactory Difficult Impassable e Lane (Frogpon 11 due to fallen t	ilty % 100 0 d) to jurees an	Sign P Ideal No In place Needed nct with FP d debris that	2 1 1 Tis77 (1	Sign Ideal No In place Needed I2 Acre Copse	nage Provisi Acc Signs 0 0 0 0 0 0 0.33 km.) C	ion W Markers 7 3 4 OS Ref: 9512	Stiles Total No Need repair Need renewal 265 to 948265	Stiles 1 0 0	1 0	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs,WC and HG; Action Needed: Sleeper causeway needs to be longer; A post waymarker is needed to indicate direction of FP 11 from TIS77 FP to	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting. Either a New Post from Tis77 or at least a waymark disc needed
Parish Footpath FP11 Ansty Coombe Poor access via FP1 Parish Footpath	Accessib Satisfactory Difficult Impassable e Lane (Frogpon 11 due to fallen t	ilty % 0 100 0 d) to jurees an	Sign P Ideal No In place Needed nct with FP d debris that	2 1 1 Tis77 (1	Sign Ideal No In place Needed I2 Acre Copse	nage Provisi Acc Signs 0 0 0 0 0 0.) 0.33 km.) 0 since 2103 nage Provisi	ion W Markers 7 3 4 OS Ref: 9512	Stiles Total No Need repair Need renewal 265 to 948265	Stiles	1 0 0	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs, WC and HG; Action Needed: Sleeper causeway needs to be longer; A post waymarker is needed to indicate direction of FP 11 from TIS77 FP to Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015 Avs + WC. Other stile off	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting. Either a New Post from Tis77 or at least a waymark disc needed Observations
Parish Footpath FP1 1 FP11 Ansty Coombe	Accessib Satisfactory Difficult Impassable e Lane (Frogpon 11 due to fallen t Accessib	ilty % 100 0 d) to jurees an ilty %	Sign P Ideal No In place Needed nct with FP d debris that	2 1 1 Tis77 (1	Ideal No In place Needed I2 Acre Copse	nage Provisi Acc Signs 0 0 0 0 0 0.33 km.) Cosince 2103 nage Provisi Acc Signs	ion W Markers 7 3 4 DS Ref: 951:	Stiles Total No Need repair Need renewal 265 to 948265 Stiles	Stiles 1 0 0 8 Gates Stiles	1 0 0	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs,WC and HG; Action Needed: Sleeper causeway needs to be longer; A post waymarker is needed to indicate direction of FP 11 from TIS77 FP to Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015 Avs + WC. Other stile off Ansty Coombe near The Hundred repaired	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting. Either a New Post from Tis77 or at least a waymark disc needed Observations A well used, pleasant FP up to 12
Parish Footpath FP11 Ansty Coombe Poor access via FP1 Parish Footpath	Accessib Satisfactory Difficult Impassable e Lane (Frogpon 11 due to fallen t Accessib	ilty	Sign P Ideal No In place Needed nct with FP d debris that Sign P	2 1 1 Tis77 (1	Ideal No In place Needed I2 Acre Copse mained there s Sign	nage Provisi Acc Signs 0 0 0 0 0.00.33 km.) Cosince 2103 nage Provisi Acc Signs 0	ion W Markers 7 3 4 DS Ref: 9512 ion W Markers 3	Stiles Total No Need repair Need renewal 265 to 948265 Stiles	\$tiles	1 0 0 Gates	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs, WC and HG; Action Needed: Sleeper causeway needs to be longer; A post waymarker is needed to indicate direction of FP 11 from TIS77 FP to Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015 Avs + WC. Other stile off Ansty Coombe near The Hundred repaired by landowner in C 2012/3 after falling tree	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting. Either a New Post from Tis77 or at least a waymark disc needed Observations A well used, pleasant FP up to 12
Parish Footpath FP11 Ansty Coombe Poor access via FP1 Parish Footpath	Accessib Satisfactory Difficult Impassable e Lane (Frogpon 11 due to fallen t Accessib Satisfactory Difficult Impassable	ilty	Sign P Ideal No In place Needed nct with FP d debris that Sign P Ideal No In place Needed	2 1 1 Tis77 (1 t has re osts 1 1 0	Ideal No In place Needed I2 Acre Copse mained there s Sign Ideal No In place Needed	nage Provisi Acc Signs 0 0 0 0 0 0.) 0.33 km.) Cosince 2103 nage Provisi Acc Signs 0 0 0	ion W Markers 7 3 4 DS Ref: 9512 ion W Markers 3 2 1	Stiles Total No Need repair Need renewal 265 to 948265 Stiles Total No Need repair Need repair	\$tiles	1 0 0 0 Gates 0 0 0	Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015. Avs +WC. Other stile off Ansty Coombe Lane replaced by gate in late summer 2014 plus a sleeper causeway to help walkers avoid bog conditions. Avs,WC and HG; Action Needed: Sleeper causeway needs to be longer; A post waymarker is needed to indicate direction of FP 11 from TIS77 FP to Achieved in 2014/15 Stile at entrance to 12 Acre Copse renewed in summer 2015 Avs + WC. Other stile off Ansty Coombe near The Hundred repaired	FP 11 has been blocked by fallen trees/debris since Nov/Dec 2013. Despite representations to the LandOwner, we are still waiting. Either a New Post from Tis77 or at least a waymark disc needed Observations A well used, pleasant FP up to 12

Parish Footpath	Accessib	ilty	Sign P	osts	Sig	nage Provis	ion	Stiles	& Gates		Achieved in 2014/15	Observations
		%				Acc Signs	W Markers		Stiles	Gates	Stile off Ansty Coombe Lane (top) giving	A lovely walk, linking in with Wardour
FP13	Satisfactory*	100	Ideal No	2	Ideal No	0	6	Total No	2	0	access to the Horwood Farm track renewed	Woods and Old and New Wardour
FF 13	Difficult	0	In place	1	In place	0	0	Need repair	0	0	in the summer of 2015. (Avs and WC) Other	Castle. Fantastic views of the Downs.
	Impassable	0	Needed	1	Needed	0	6	Need renewal*	1	0	Action underway. Involving alternative	*Not able to quantify acessibility in the
FP13 Ansty Coombe	e Lane (top) to H	orwood	d Farm. 0.89	km. OS	Ref: ST 9472	60 to 940255					permissive FPs and access	case of FP13 but there is good access
Parish Footpath	Accessib	ilty	Sign P	osts	Sig	nage Provis	ion	Stiles	& Gates		Achieved in 2014/15	Observations
		%				Acc Signs	W Markers		Stiles	Gates		A 'locals' walk. Super views of the
FP14	Satisfactory	100	Ideal No	2	Ideal No	0	11	Total No	4	0		Coombe. Safe alternative to the
FF 14	Difficult	0	In place	2	In place	0	0	Need repair	0	0		narrow lane and Frogpond bend
	Impassable	0	Needed	0	Needed	0	11	Need renewal	1	0		
FP14 Ansty Coombe									& Gates		Achieved in 2014/15	Observations
Parish Footpath	Accessib	-	Sign P	osts	Sig	nage Provisi		Stiles		0.4		Observations A year about track coation linking with
	0 " ()	%		4		Acc Signs		TILL		Gates	New gate replaced a stile along boundary with Thatchers Cottage. Replaced by Avs	A very short track section linking with several other FPs within Ansty
FP15	Satisfactory	100	Ideal No	1	Ideal No	0	2	Total No	0	1	and Derek from WC., The old signpost	Coombe. Nice and tidy.
	Difficult	0	In place	1	In place	0	0	Need repair	0	0	looks worse for wear and probably needs	
	Impassable	0	Needed	1	Needed	0	2	Need renewal	1	0	replacing.	
FP15 Track pat That	tchers Cottage to	Kings	Lane. 0.11k	m. OS I	Ref: ST 950266	to 951267						
Parish Footpath	Accessib	ilty	Sign P	osts	Sig	nage Provis	ion	Stiles	& Gates		Achieved in 2014/15	Observations
		%				Acc Signs	W Markers		Stiles	Gates	Action Needed: 2 post markers needed to	Deep rolling ruts on the byway here
FP16	Satisfactory	100	Ideal No	0	Ideal No	0	0	Total No	0	0	link FP 5 with byway (FP 16 - Ansty section)	but generally satisfactory. Difficulties
1 F 10	Difficult	0	In place	0	In place	0	0	Need repair	0	0	with ALV15 bridleway to Berwick St John.	here differentating between bridleway
	Impassable	0	Needed	0	Needed	0	0	Need renewal	0	0	See FP5	access and FP access

Parish Footpath	ath Accessibilty		Sign Posts		Sig	nage Provisio	Stiles & Gates			Achieved in 2014/15	Observations	
		%				Acc Signs V	N Markers		Stiles	Gates		A two way sign will be needed w
FP17	Satisfactory	100	Ideal No	3	Ideal No	4	2	Total No	0	0		FP5 meets FP 17
FP I I	Difficult	0	In place	2	In place	0	0	Need repair	0	0		
	Impassable	0	Needed	1	Needed	4	2	Need renewal	0	0		
FP17 (Shave Lane) f	from foot of Ans	ty Dow	n (old lime k	iln area	to Ansty Bou	undary just be	efore Shas	ton-Salisbry by	ay. 0.82	km		
OS Ref: ST 9532511	to 061240											
JO Nel. OT 3332311	10 901240											
Parish Footpath	Accessib	ilty	Sign P	osts	Sig	nage Provisio	on	Stiles	& Gates		Achieved in 2014/15	Observations
		ilty %	Sign P	osts	Sig	nage Provisio				Gates	Achieved in 2014/15	Observations
Parish Footpath		•	Sign P	osts 0	Sig					Gates 0	Achieved in 2014/15	Observations
	Accessib	%			_		N Markers		Stiles		Achieved in 2014/15	Observations
Parish Footpath	Accessib Satisfactory	% 100	Ideal No	0	Ideal No	Acc Signs V	N Markers 2	Total No	Stiles 0	0	Achieved in 2014/15	Observations
Parish Footpath	Accessib Satisfactory Difficult Impassable	% 100 0 0	Ideal No In place Needed	0 0 0	Ideal No In place Needed	Acc Signs V 0 0 0	W Markers 2 0 2	Total No Need repair Need renewal	Stiles 0 0 0	0 0 0	Achieved in 2014/15	Observations

Analysis October 2015	ALL PATHS											
Total Dist (km)	Accessibility	%	Sign Posts		Signage	Acc Signs W	/ Markers	Stiles & Gates	Stiles	Gates	Achievements 2014-2015	WC – Wiltshire Council
8.65 km (5.8 miles)	Satisfactory	81	Ideal No	32	Ideal No	11	90	Total No	36	4	sections of path cleared 4	Avs – Ansty Volunteers
	Difficult	13	In place	18	In place	0	16	Need repair	7	0	new stiles installed 8	HG - Heavy Gang
	Impassable	6	Needed	15	Needed	11	74	Need renewal	12	0	new gates installed 2	